Unidentified Traffic Sighting by Japan Airlines Flight 1628 November 18, 1986 ANC ARTCC

Index

Tab 1

Tab 2 Chronology of Events Transcription Tab 3 Flight Path Chart Tab 4 Personnel Statements Tab 5 Daily Record of Facility Operations, Tab 6 FAA Form 7230-4 Position Logs, FAA Form 7230-10 Tab 7 ZAN EARTS Continuous Data Recordings, Tab 8 (radar tracking data).



Memo

Anchorage ARTCC 5400 Davis Hwy. Anchorage, Alaska

Subject:

INFORMATION: Transcription concerning the

Date:

January 9, 198

incident involving Japan Airlines Flight 1628 on November 18, 1986 at approximately 0218 UTC.

From:

Quentin J. Gates Air Traffic Manager,

Reply to Attn. of:

ANC ARTCC

To:

This transcription covers the time period from November 18, 1986, 0214 UTC to November 18, 1986, 0259 UTC.

Agencies Making Mar	• .
Agencies Making Transmissions	Abbreviations
Japan Airlines Flight 1628	JL1628
Anchorage ARTCC Combined Sector R/D15	R/D15
Anchorage ARTCC Sector D15	D15
Anchorage ARTCC Sector R15	R15
Regional Operations Command Center	ROCC
United Airlines Flight 69	
TOTEM71	UA69
	TOTEM
Fairbanks Approach Control	АРСН

I hereby certify that the following is a true transcription of the recorded conversations pertaining to the subject incident:

Anthory M. Wylie

Quality Assurance Specialist

Anchorage ARTCC





Memorandum

Federal Aviation Administration

Subject:

From:

INFORMATION: Unidentified Traffic Sighting

by Japan Airlines

Date: DEC 1 8 1986

Air Traffic Manager, Anchorage ARTCC, ZAN-1

Reply to Attn. of;

To: Manager, Air Traffic Division, AAL-500 ATTN: Evaluation Specialist, AAL-514

The attached chronology summarizes the communications and actions of Japan Airlines Flight 1628 on November 18, 1986.

Radar data recorded by Anchorage Center does not confirm the presence of the traffic reported by Flight 1628. No further information has been received from civil or military sources since the date of the sightings.

Major Johnson of the Elmendorf Regional Operations Command Center (ROCC) is checking their records and the operations personnel for further details. He will forward any additional information to Anchorage Center as soon as possible.

Should you have any questions or need additional information, contact Tony Wylie, Quality Assurance Specialist, 269-1162.

Original signed by

Quentin J. Gates

Attachment



The following is a chronological summary of the alleged aircraft sightings by Japan Airlines Flight 1628, on November 18, 1986:

All times listed are approximate UTC unless otherwise specified.

- 0219 The pilot of JL1628 requested traffic information from the ZAN Sector 15 controller. When the controller advised there was no traffic in the vicinity, JL1628 responded that they had same direction traffic, approximately 1 mile in front, and it appeared to be at their altitude. When queried about any identifiable markings, the pilot responded that they could only see white and yellow strobes.
- 0225 JL1628 informed ZAN that the traffic was now visible on their radar, in their 11 o'clock position at 8 miles.
- 0226 ZAN contacted the Military Regional Operations Control Center, (ROCC), and asked if they were receiving any radar returns near the position of JL1628. The ROCC advised that they were receiving a primary radar return in JL1628's 10 o'clock position at 8 miles.
- 0227 The ROCC contacted ZAN to advise they were no longer receiving any radar returns in the vicinity of JL1628.
- 0231 JL1628 advised that the "plane" was "quite big", at which time the ZAN controller approved any course deviations needed to avoid the traffic.
- 0232 JL1628 requested and received a descent from FL350 to FL310. When asked if the traffic was descending also, the pilot stated it was descending "in formation".
- 0235 JL1628 requested and received a heading change to two one zero. The aircraft was now in the vicinity of Fairbanks and ZAN contacted Fairbanks Approach Control asking if they had any radar returns near JL1628's position. The Fairbanks Controller advised they did not.
- 0236 JL1628 was issued a 360 degree turn and asked to inform ZAN if the traffic stayed with them.
- 0238 The ROCC called ZAN advising they had confirmed a "flight of two" in JL1628's position. They advised they had some "other equipment watching this", and one was a primary target only.
- 0239 JL1628 told ZAN they no longer had the traffic in sight.
- 0242 The ROCC advised it looked as though the traffic had dropped back and to the right of JL1628, however, they were no longer tracking it.
- 0244 JL1628 advised the traffic was now at 9 o'clock
- 0245 ZAN issued a 10 degree turn to a northbound United Airlines flight, after pilot concurrence, in an attempt to confirm the traffic.
- 0248 JL1628 told ZAN the traffic was now at 7 o'clock, 8 miles.

0250 - The northbound United Flight advised they had the Japan Airlines flight in sight, against a light background, and could not see any other traffic.

0253 - JL1628 advised they no longer had contact with the traffic.

A subsequent review of ANC ARTCC's radar tracking data failed to confirm any targets in close proximity to JL1628.